Oil Field Environmental Incident Summary

Responsible Party: EOG RESOURCES, INC. **Well Operator:** EOG RESOURCES, INC.

Well Name: GRAIL 200-02 SWD

Field Name: SPOTTED HORN Well File #: 90245

Date Incident: 6/5/2014 Time Incident: 09:48 Facility ID Number:

County: MCKENZIE Twp: 150 Rng: 95 Sec: 2 Qtr: SE SE

Location Description:

Submitted By: Keith Kallberg Received By:

Contact Person: Keith Kallberg

600 17TH ST STE 1000N DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 2.5 Barrels 2.5 Barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

N/A

Areal Extent:

Location surface NE of the pump building.

Potential Environmental Impacts:

N/A

Action Taken or Planned:

Hotoil treatment was stopped, vac truck onsite was able to remove the free fluid. Cleanup crew was contacted to scrape, remove & replace the affected material.

Wastes Disposal Location: Fluids were put into the Grail SWD, solids will be taken to Clean

Harbors at Sawyer ND.

Agencies Involved:

Updates

Date: 6/5/2014 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

2.5 barrels of oil released and recovered on well/facility according to spill report. NDIC retains oversight.